

TS 4000
TS 4000 S

107754-02





GEZE



A


B



TS 4000/4000 S $a \leq 1400 \text{ mm}$
TS 4000 EN 5-7 $a \leq 1600 \text{ mm}$

TS 4000/4000 S $a \leq 1400 \text{ mm}$
TS 4000 EN 5-7 $a \leq 1600 \text{ mm}$




1





i

CE	GEZE GmbH P.O. Box 1363 71226 Leonberg	12	
0672-CPD-0050	EN 1154	4 8 6/1 1 1 4	TS 4000
Substanz: -----	EN 1154	4 8 7/5 1 1 4	TS 4000 EN 5-7
	EN 1154	4 8 6/2 1 1 4	TS 4000 S





2





[mm]





4x
5x60
4x
M5x55



[mm]





4x
5x35
4x
M5x20





3x
M5x45



3




4







5





6





i+ TS 4000




i+ TS 4000 S





7




a (mm) - EN	
1600	7
1400	6
1250	5
1150	4
950	3
850	2
750	1





8




i+ TS 4000 S




9










i



TS 4000/4000 S a ≤ 1400 mm
TS 4000 EN 5-7 a ≤ 1600 mm



TS 4000/4000 S a ≤ 1400 mm
TS 4000 EN 5-7 a ≤ 1600 mm



GEZE GmbH

P.O.Box 1363
Reinhold-Vöster-Straße 21-29
71229 Leonberg
Germany

Tel.: 0049 7152 203-0
Fax: 0049 7152 203-310
www.geze.com

107754-02



GEZE